

ANNEX 2

TYPICAL CONDITION PHOTOGRAPHS



Downstream length: hole in wall & bank



Downstream length: general view



Downstream length: tree damage



Downstream length: cracked wall



Upstream length: previous repair with hole in bank. Currently repairable



Upstream length: hole in bank covered with steel mesh fence



Upstream length: failed repair, replacement required



Upstream length: repairable length with failed length beyond