

LOCATION PLAN


KEY:

- 2 Existing Defects (recorded in 2002)
- 7 New Defects (recorded in 2009)

NOTES:

- 1.
- 2.
- 3.

C	Client	City of York
B	Contractor	City of York
A	Design	City of York
O	Operation	City of York
Maint	Maintenance	City of York
Rev	Revision	City of York
Proj	Project	City of York
Drawn by:	Checked by:	Scale: 1:1000
Drawn by: JGC	Checked by: JGC	Date: 14/10/20
Project Name:	Project No.:	Revision:
RIVER OUSE BANK REPAIRS	10434	3
Drawing Title:	Defects Location Plan:	Revision Letter:
	Clifton Long Reach	A2
Scale:	Drawn by:	Checked by:
1:2500	JGC	JGC
Drawn by:	Checked by:	Scale:
JGC	JGC	1:1000
Date:	Date:	Date:
14/10/20	14/10/20	14/10/20
Project Name:	Project No.:	Revision:
RIVER OUSE BANK REPAIRS	10434	3
Drawing Title:	Defects Location Plan:	Revision Letter:
	Clifton Long Reach	A2
Scale:	Drawn by:	Checked by:
1:2500	JGC	JGC
Drawn by:	Checked by:	Scale:
JGC	JGC	1:1000
Date:	Date:	Date:
14/10/20	14/10/20	14/10/20



Defect Location Plan (Scale : 1/2500 @ A2)