

## ANNEX C

Site	Type	Spaces	Racks	Condition	CCTV?	Distance to street light	Other comments
SLP car park - toastrack nr ticket m/c	Sheff stand - toastrack	10	5	v. good	No	15m	Overlooked by council offices
SLP car park - stands nr ticket m/c	Sheff stands	4	2	good (both slightly bent)	Barely	12m	Overlooked by council offices
SLP car park - stands nr Mayor's space	Sheff stands	8	4	good (need cleaning)	Barely	<5m	Well used, overlooked by passers-by
Exhibition Square	Sheff stand - toastrack	8	4	v.good	Yes	20m	Well used, overlooked by passers-by
Gillygate - Miller's Yard	Sheff stands	6	3	Good	No	10m	Overlooked by adjacent units, half of which are empty, public probably not aware of location
Union Terrace Car Park - south end	Sheff stands	8	4	2 bent, 2 ok	No	10m	Badly positioned, too close to kerb, need protecting from vehicles
Union Terrace Car Park - north end	Sheff stands	12	6	2 bent, 4 ok	Yes	15m	Badly positioned, too close to kerb, need protecting from vehicles
Sainsburys - near car park ramp	Sheff stands	12	6	good	?	10m	Not well used, too far away from shop entrance
Sainsburys - near flats	Sheff stands	12	6	mostly good, 1 has saw mark	?	10m	Very well used by customers and staff
Sainsbury - near front entrance	Sheff stands	10	5	good	?	10m	Very well used by customers and staff
Sainsburys - near side exit	Sheff stands	14	7	good	?	10m	Only used when other racks nearer to front entrance full
Sainsburys - near car park entrance	Sheff stands	6	3	2 good, 1 looks loose	?	10m	Not well used, too far away from shop entrance
Bedern passage to side of Caesars	Wall Bar	1	1	good	No	5m	Well used
College Street / Goodramgate junc	Sheff stands	20	10	most good / 1 loose	No	10m	Over-subscribed, re-cement in loose one

## ANNEX C

Site	Type	Spaces	Racks	Condition	CCTV?	Distance to street light	Other comments
Low Petergate / Duncombe Place junc	Sheff stands	12	6	good, plastic peeling	No	<5m	Massively over-subscribed, overlooked by passers-by
Blake Street - Assembly Rooms side	Sheff stand - toastrack	24	12	Good	No	12m	Very well used, overlooked by passers-by
Blake Street - Fruit Shop side	Sheff stand - toastrack	30	15	Good but paint flaking	No	<5m	Very well used, overlooked by passers-by
Blake Street - opp Red House	Sheff stands	10	5	V.good	No	<5m	Very well used, overlooked by passers-by
Davygate - side of church	Sheff stands	20	10	Good, paint flaked off	Yes	<5m	Well used especially by unconventional bikes & mopeds, galv racks
Davygate - outside JJB	Sheff stands	28	14	Most going rusty - 4 galv ones OK	Yes	7m	Very well used, overlooked by passers-by, space for removed one to be replaced
Davygate - near New Street junc	Sheff stands	24	12	Good but plastic coming off	Yes	10m	Very well used, overlooked by passers-by
St Sampson's Square - north of toilet	Butterfly wheel grips	10	10	Good	Yes	10m	Very well used, overlooked by passers-by
St Sampson's Square - south of toilet	Butterfly wheel grips	5	5	Good	No	10m	Very well used, overlooked by passers-by
Parliament Street - north of fountain	Sheff stands	52	26	Rusty but metal still sound	No	<5m	Very well used, overlooked by passers-by
Parliament Street - south of fountain	Sheff stands	46	23	Rusty but metal still sound	No	<5m	Very well used, overlooked by passers-by
Whip-ma-whop-ma-gate - Halifax side	Sheff stands	12	6	Rusty but metal still sound	No	10m	Very well used, overlooked by passers-by
Whip-ma-whop-ma-gate - church side	Sheff stands	24	12	Rusty but metal still sound	Yes	<5m	Well used, overlooked by passers-by
Goodramgate mid section	Sheff stands	4	2	V. good	Barely	<5m	Very well used, overlooked by passers-by

## ANNEX C

Site	Type	Spaces	Racks	Condition	CCTV?	Distance to street light	Other comments
St Andrewgate	Sheff stands	58	29	Rusty but metal still sound	No	5m	Very well used, less overlooked by passers-by
Stonebow - adj Fibbers stairs	Sheff stands	8	4	Good	No	20m	Not used, virtually out of view of public and not overlooked
Stonebow - nr Black Horse Passage	Butterfly wheel grips	2	2	Good	No	10m	Well used, overlooked by bus queue
Piccadilly - nr Multiyork shop	Sheff stands	12	6	Rusty but metal still sound	Yes	15m	Well used, overlooked by bus queue
Piccadilly - opp car park	Sheff stands	4	2	Rusty but metal still sound	Yes	15m	3 racks appear to have been cut off, was this done on purpose?
Merchantgate	Sheff stands	36	18	Very Rusty but metal still sound	No	10m	Well used, overlooked by bus queue
Walmgate / Merchantgate junc	Sheff stands	4	2	Good	No	10m	Fairly well used, overlooked by adjacent shops
Walmgate shops 1	Butterfly wheel grips	8	8	Good	No	<5m	Not very well used, despite being overlooked by shops
Walmgate shops 2?	Butterfly wheel grips	5	5	Good	No	<5m	Not very well used, despite being overlooked by shops
Walmgate shops 3?	Butterfly wheel grips	5	5	Good	No	<5m	Not very well used, despite being overlooked by shops
Walmgate / Huby Court shops 1	Butterfly wheel grips	5	5	Good	No	<5m	Not very well used, despite being overlooked by shops
Walmgate / Huby Court shops 2	Butterfly wheel grips	8	8	Good	No	<5m	Not very well used, despite being overlooked by shops
Barbican - adj swimming pool	Sheff stands	38	19	Very Rusty but metal still sound	No	15m	Not used, not overlooked
Barbican - entrance left	Sheff stands	4	2	Rusty but metal still sound	No	20m	Would be used if centre was open

## ANNEX C

Site	Type	Spaces	Racks	Condition	CCTV?	Distance to street light	Other comments
Barbican - entrance right	Sheff stands	24	12	Rusty but metal still sound	No	10m	Would be used if centre was open
Tower Gardens	Sheff stands	10	5	V.good	No	10m	Well used during day
Castle Car Park / Fairfax House	Butterfly wheel grips	25	25	Good	Yes	5m	Three batches, 8 + 9 + 8
Friargate / Friends Meeting House	Sheff stands	20	10	good, plastic peeling	No	10m	Well used
Clifford Street o/s job centre	Sheff stands	14	7	1 loose, others a bit rusty	No	<5m	Not so well used, not a very inviting location
Cumberland Street	Sheff stands	16	8	good, plastic peeling	No	<5m	Well used
King's Staith - nr Lowther PH	Sheff stands	10	5	good, plastic peeling	Barely	10m	Well used
South Esplanade - nr boat hire	Sheff stands	24	12	V.good	Barely	<5m	Well used in tourist season when overlooked by boat hire
Queen's Staith	Sheff stands	40	20	V.good (galv)	Yes	<5m	Hardly used at all, looks a bit isolated
The Priory - junc North St / Micklegate	Sheff stands	12	6	good, plastic peeling	Barely	10m	Fairly well used, overlooked by passers-by
Micklegate - o/s Blakehead bookshop	Sheff stands	10	5	Good	Barely	15m	Very well used, overlooked by adjacent shops
Rougier Street - o/s Macmillans (BPM)	Sheff stands	18	9	good, plastic peeling	Yes - not CYC	7m	Fairly well used, overlooked by bus queue
Tanner's Moat - opp The Maltings	Sheff stands	38	19	good, plastic peeling	No	7m	Very well used, overlooked by passers-by
Tanner's Moat - opp Norwich Union	Sheff stand - toastrack	8	4	Good but base plate bent	No	10m	A bit secluded at night when less through traffic

## ANNEX C

Site	Type	Spaces	Racks	Condition	CCTV?	Distance to street light	Other comments
Esplanade - nr Rowing Club	Sheff stand - toastrack	16	8	Good	No	<5m	A bit secluded at night when less through traffic
Station - nr Tea Room Square	Sheff stands	8	4	V.good	No	<5m	Over-subscribed
Station - on platform	Sheff stands	370	185	Old ones OK, new ones v.good	Yes	5m	Very well used, several abandoned bikes need dealing with to free up spare capacity for others
Museum Gardens	Sheff stands	8	4	Good	No	8m	Usually overlooked by adjacent Park & Ride queue but a bit secluded
Library - left of main door	Sheff stands	14	7	Good	No	20m	Very well used by library and finance centre customers
Library - right of main door	Sheff stands	12	6	Good	No	20m	Very well used by library and finance centre customers